Deterioration of building envelope of wooden apartment buildings built before 1940 based on external survey

Paul Klõšeiko, Tõnis Agasild, Targo Kalamees Chair of Building Physics and Architecture, Tallinn University of Technology, Estonia

Introduction

- Wood was the main structural building material until WW II.
- Many of the historic listed buildings and areas are in bad conditions and need thorough and ongoing renovation.
- A lack of local guidelines aimed at increasing durability and energy-efficiency as well to longer the service life of monumental building or milieu valuable districts;







Introduction

- Wood was the main structural building material until WW II.
- Many of the historic listed buildings and areas are in bad conditions and need thorough and ongoing renovation.
- A lack of local guidelines aimed at increasing durability and energy-efficiency as well to longer the service life of monumental building or milieu valuable districts;
- This study concentrates on the:
 - •investigation of technical conditions of the external side of the building envelope (roof, facades, windows, foundations etc.) of old wooden apartment buildings;
 - moisture-related problems mainly.

Studied buildings

- ■4 towns
- private ownership
- ■1-4 stories
- ■built <1940
- external wall
 - ■hor. log
 - ■vert. log
 - ■timber-frame
- external surface:
 - ■wooden gladding (73%)
 - ■plastering (27%)









- Studied buildings
- The survey
 - External survey: 133 buildings;
 - ■External + internal survey: 29 buildings;
 - Special questionnaire (in beginning two researchers, later more);



- Facade: material, decorations, condition, windows, doors, maximum thickness of additional thermal insulation;
- ■Rainwater drainage systems: existence of the components, condition;
- Roof: material, leaks, condition;
- ■Chimney: existence of the components, condition;
- Recommendations: required tasks to be attended and timeframe.



- Studied buildings
- The survey
 - External survey: 133 buildings;
 - External + internal survey: 29 buildings;
 - Special questionnaire (in beginning two researchers, later more);
 - Samples from possibly damaged areas;






- Studied buildings
- The survey
- Classification for technical condition
 - 0 failure/dangerous situation, very severe damage: needs immediate renovation;
 - 1 bad, severe damage:needs renovation during 1 year;
 - 2 satisfactory, moderate damage: renovation recommended within 3-5 years;
 - 3 good, slight damage: maintenance recommended within 5 years;
 - 4 very good, very slight and small damage: may need maintenance within 10 years;
 - 5 excellent, no visible damage, new structure in good condition, correct performance.

Foundation's board















Results: roof

- Typical problems:
 - Leaking of roof:
 - **■**corrosion of metal,
 - ecracking of the roof-boards,
 - ■loose or missing roofing tiles.
 - bushings;
 - Flora on the roof
 (prevents water drainage;
 50 % of stone and asbestos-cement roofs suffered from growth of moss or plants);
 - Lack of maintenance;













Results: roof

- Typical problems:
 - Leaking of roof:
 - **■**corrosion of metal,
 - cracking of the roof-boards,
 - ■loose or missing roofing tiles.
 - bushings;
 - Flora on the roof (prevents water drainage; 50 % of stone and asbestos-or roofs suffered from growth of or plants);
 - Lack of maintenance;
 - Low thermal resistance:





# M				
Type of roofing material	Standing seam	Asbestos-	Corrugated	Stone
	sheet metal	cement board	sheet metal	roofing
Percentage of roofing materials (note: several materials could be present on a roof simultaneously)	54 %	35%	15%	9%
Average category of the	Good	Satisfactory	Very good	Good
technical condition	(cat. 3)	(cat. 2)	(cat. 4)	(cat. 3)
Roofs in bad or dangerous condition, (cat. 0 and 1)	3 %	4 %	0 %	0 %
Roofs requiring replacement within 3 years (cat. 2)	13 %	35 %	0 %	25 %
Roofs requiring replacement within 10 years	33%	48%	0%	17%

Results: rainwater drainage systems

- 72% of rainwater drainage systems were defective:
 - non vandal-proof lower sections of the drainage pipes
 - water reached foundation wall and external wall,
 - construction errors (pipes connected in the wrong order),
 - growth of flora and low maintenance.













Results: rainwater drainage systems

- 72% of rainwater drainage systems were defective:
 - non vandal-proof lower sections of the drainage pipes
 - water reached foundation wall and external wall,
 - construction errors (pipes connected in the wrong order),
 - growth of flora and low maintenance.







	Rainwater flow to the	Defects and	Clogging of the
	external wall or	discontinuance of	rainwater
	foundation wall	rainwater systems	systems
Of all rainwater drainage systems	62 %	44 %	29 %
Of renovated rainwater drainage systems	40 %	21 %	14 %

Results: facades

- Main areas of damages:
 - ■above foundation wall: 48%
 - ■around eaves: 30%
 - ■near drainage system: 26%
 - ■near corners: 21%
 - ■around canopies: 11%
 - ■near trees and vegetation: 9%
 - ■around windows: 8%
 - near cables with wrong slope













Results: foundations

- Main damages:
 - excess moisture (chipping of paint, destroyed mortar, bricks and limestone): 58%
 - ■algae as an indicator of moist surface: 57%
 - different settlement of foundation: 32%
 - high level of the ground surface: 8%













Results: foundations

- Main damages:
 - excess moisture (chipping of paint, destroyed mortar, bricks and limestone): 58%;
 - ■algae as an indicator of moist surface: 57%
 - different settlement of foundation: 32%
 - high level of the ground surface: 8%
- Reasons for the wetting of the foundation:
 - ■rainwater downpipe: 35%
 - ■vegetation: 22%
 - missing or broken gutter: 20%
 - water sprays from the street: 14%
 - ■flows down the wall: 14%
 - wrong street's slope: 13%







Results: facade + foundations

Typical area for damage: the rows first of the log of the external wall;
















Results: facade + foundations

- Typical area for damage:
 the rows first of the log of the external wall;
- In renovation of buildings, the Heritage Board requires original solution

(despite that was partly guilty on degradation);





Results: rot damages

- 27% of wooden samples had rot damages:
 - ■brown rot: 20%,
 - ■soft rot: 5%,
 - ■white rot: 2%.
- Rot damage was determined in 63% of buildings (10/16).
- Main areas for rot damages:
 - the first log row of the external wall,
 - roofing construction,
 - floor beams in crawl space.






Conclusions

Wood is not very moisture-tolerant and brings easily all mistakes out;

The most critical factor in degradation of wooden buildings was free water;

 Nevertheless, in many cases designers still concentrate mainly on vapour diffusion;



moisture damages

Required renovation within 10 years:

New	New	Foundation wall	New	At least 3 of the
cladding	roofing	renovation	windows	previous combined
37%	52%	71%	17%	23%